

**CARELESSNESS CAUSES FIRE**

BATCH/I.D. No.....

TO COMPLY WITH THE FURNITURE AND FURNISHINGS (FIRE) (SAFETY) REGULATIONS 1988:

THIS ITEM DOES NOT INCLUDE A SCHEDULE 3 INTERLINER. ALL FOAMS, FILLINGS & COMPOSITES HAVE BEEN TESTED BY OUR SUPPLIER(S) TO ENSURE COMPLIANCE WITH THE RELEVANT IGNITABILITY TEST. COVERS & FILLINGS ARE CIGARETTE RESISTANT. COVERS ARE MATCH RESISTANT.

FURTHER DETAILS ARE AVAILABLE FROM YOUR RETAILER.

PL21A

**CARELESSNESS CAUSES FIRE**

Batch / I.D. No.

To comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988:

This item does not include a Schedule 3 interliner.

All foams, fillings and composites comply with the relevant ignitability test.

Covers and fillings are cigarette resistant.

Covers are match resistant.

Further details are available from your retailer.



**CARELESSNESS CAUSES FIRE**


BATCH/I.D. No.....

TO COMPLY WITH THE FURNITURE AND FURNISHINGS (FIRE) (SAFETY) REGULATIONS 1988:

THIS ITEM DOES/DOES NOT INCLUDE A SCHEDULE 3 INTERLINER. ALL FOAMS FILLINGS & COMPOSITES HAVE BEEN TESTED BY OUR SUPPLIER(S) TO ENSURE COMPLIANCE WITH THE RELEVANT IGNITABILITY TEST. COVERS & FILLINGS ARE CIGARETTE RESISTANT. COVERS ARE/ARE NOT MATCH RESISTANT

FURTHER DETAILS ARE AVAILABLE FROM YOUR RETAILER

**MATTRESS TURNING INSTRUCTIONS**



In order to provide the longest life possible for your bed, please turn this mattress so that this label appears in the lower left hand corner of the bed during the months listed below:-

**JULY • AUGUST • SEPTEMBER**